This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (L
Ref. No. 0212.69069
Replacement Sheet 1 of 13


(Lawrence J. Crain) (312) 360-0080



EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 2 of 13


(Lawrence J. Crain) (312) 360-0080





EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 3 of 13

(Lawrence J. Crain) (312) 360-0080




EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (L
Ref. No. 0212.69069
Replacement Sheet 4 of 13 3/15/04 (Lawrence J. Crain) (312) 360-0080 MAR 1 8 2004 Fig. 6

EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (1
Ref. No: 0212.69069
Replacement Sheet 5 of 13

(Lawrence J. Crain) (312) 360-0080




FIG.7



EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 6 of 13

(Lawrence J. Crain) (312) 360-0080


FIG.8



EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 7 of 13


(Lawrence J. Crain) (312) 360-0080






3/15/04






3/15/04





EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 10 of 13

3/15/04



MAR 1 8 2004

134

EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd.
(Ref. No. 0212.69069
Replacement Sheet 11 of 13


3/15/04

(Lawrence J. Crain) (312) 360-0080

128

524b 538 FIG.13
524b 538 FIG.13
524b 538 524a 540 556 546


132



3/15/04

(Lawrence J. Crain) (312) 360-0080

EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (Lef. No. 0212.69069
Replacement Sheet 12 of 13



EXTENSION CORD RETENTION AND PLUG...
Wascow et al.
Greer, Burns & Crain, Ltd. (I
Ref. No. 0212.69069
Replacement Sheet 13 of 13



